

Attachment 3 – Current Photographs

Figure 1: Main facade. Source: Site Visit with Franco Valeriote, 2009.



Figure 2: Close-up of tower on main facade. Source: Site Visit with Franco Valeriote, 2009.



Figure 3: Enclosed Verandah and protruding gable with carved cornice and brackets. Source: Site Visit with Franco Valeriote, 2009.



Figure 4: Northwest side of building, original limestone façade. Source: Site Visit with Franco Valeriote, 2009.

