



Attachment-8 Interior Photos (April 2017)


Front hall with stairway and plaster cavetto crown moulding



Upper hall stair railing and door to attic



Plaster cavetto crown mouldings in both upper bedrooms



North window in attic



North room in basement with exposed heavy timber summer beam in ceiling

