

Figure 3 - Fire Insurance Plan of the City of Guelph illustrating the empty lot at 47 Alice Street, November 1907 (City of Guelph)




Figure 4 – Detail of Fire Insurance Plan of the City of Guelph showing the locations of the dwelling and shoe repair shop within 47 Alice Street in October 1929 (Guelph Civic Museum)





Figure 5 – Black and white photo of 47 Alice Street in the 1920s (Gayle Valeriote)



Figure 6 – Photo of Vincenzo Valeriote in the Shoe Repair shop on 47 Alice Street, date unknown (Gayle Valeriote)



Figure 7 – Photo of Valeriote children sitting on the window sill of the Valeriote shoe shop, ca. 1938 (Guelph Civic Museum 2000.38.3)



Figure 8 – Photo of Vincenzo Valeriote at the rear of the shoe shop, date unknown (Gayle Valeriote)





Figure 9: Photo of shoe shop on 47 Alice Street, ca. 1950s (Valeriotte 2010)



Figure 10 – Photo of residence on 47 Alice Street, ca. 1975 (Gordon Couling 1975)



Figure 11 – Photo of shoe shop on 47 Alice Street, ca. 1975 (Gordon Couling 1975)