

Attachment-1 Current Photos



Figure 1: View from south. (Photo: S. Robinson, 2023)



Figure 2: View from southeast. (Photo: S. Robinson, 2023)





Figure 3: View from east. (Photo: S. Robinson, 2023)



Figure 4: View of rear (north) corner. (Photo: S. Robinson, 2023)





Figure 5: View of corner building from west. (Photo: S. Robinson, 2023)



Figure 6: View from southwest. (Photo: S. Robinson, 2023)





Figure 7: View of front store window corner entrance from south. (Photo: S. Robinson, 2023)



Figure 8: Datestone. (Photo: S. Robinson, 2023)





Figure 9: Arthur Street N store window. (Photo: S. Robinson, 2023)



Figure 10: Brick arch over Arthur Street N door. (Photo: S. Robinson, 2023)





Figure 11: Coupled windows facing Arthur St N. (Photo: S. Robinson, 2023)



Figure 12: Coupled windows facing Eramosa Road. (Photo: S. Robinson, 2023)



Figure 13: Eramosa Road elevation. (Photo: Sr. Robinson, 2023)





Figure 14: North addition. (Photo: S. Robinson, 2023)



Figure 15: View of stable building from south. (Photo: S. Robinson, 2023)



Figure 16: View of stable building from west. (Photo: S. Robinson, 2023)