

## Attachment 2 – Current Photographs



Figure 1: 49 Metcalfe viewed from across Parkholm Ave



Figure 2: 49 Metcalfe viewed from the corner of Parkholm Avenue and Metcalfe Street



Figure 3: Curved exterior wall, stepped windows, and corner windows on the front facade of 49 Metcalfe Street



Figure 4: Front entry door with porthole window, second floor balcony with wrought iron railing, and stepped staircase window at 49 Metcalfe Street



Figure 5: Rear (north) elevation of 49 Metcalfe Street



Figure 6: Stepped staircase window on curved wall