

Attachment 1: Current Photographs, Proposed Windows/Door, and Couling Sheet



Figure 1: North Facade of the house facing Water Street. Large window to be enlarged and replaced, door to be replaced, and small window beside door to be replaced.



Figure 2: South (rear) elevation of the house showing the 1967 addition proposed for removal



Figure 3: East elevation of the residential dwelling showing the addition proposed for removal (note cinder block foundation and raised roof)



Figure 4: West elevation of the 1967 addition




Figure 5: Proposed front picture window



Figure 6: Proposed steel front door

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 76 Water Street, south side

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION about 1920

SIGNIFICANCE none

BUILDING MATERIAL ~~brick veneer and siding~~



PHOTO DATE 7-7-75

Figure 7: 76 Water Street in Couling Building Inventory.