

## Attachment-1 Current Photos

Figure 1 - View from Willow Road at Marksam Drive. (Photo: S. Robinson)



Figure 2 - View from Marksam Drive. (Photo: S. Robinson)



Figure 3 - Garage and house from Willow Road. (Photo: S. Robinson)



Figure 4 - Garage from Willow Road. (Photo: S. Robinson)



Figure 5 - House and garage from Willow Road. (Photo: S. Robinson)



Figure 6 - View east along south side of Willow Road showing stone carriage house at 404 Willow Road beyond driveway. (Photo: S. Robinson)



Figure 7 – View of house from southwest. (Photo: S. Robinson)



Figure 8 - South elevation of house. (Photo: S. Robinson)



Figure 9 – View of house from southeast. (Photo: S. Robinson)



Figure 10 – (On left) Front door and (on right) north corner of 2-storey section of house. (Photos: S. Robinson)



Figure 11 – View of 1.5-storey tail from east. (Photo: S. Robinson)



Figure 12 – View from northeast. (Photo: S. Robinson)



Figure 13 - North door in north elevation of house. (Photo: S. Robinson)



Figure 14 - North wall of east extension. (Photo: S. Robinson)



Figure 15 - North elevation of house. (Photo: S. Robinson)

