

Attachment-2 Current Photos

Figure 1 - 106 Carden Street from south. (Photo: S. Robinson, Heritage Planning)



Figure 2 - 106 Carden Street from east. (Photo: S. Robinson, Heritage Planning)



Figure 3 – Macdonell Street façade from north. (Photo: S. Robinson, Heritage Planning)



Figure 4 - View of Carden Street streetwall from railway track. (Photo: S. Robinson, Heritage Planning)



Figure 5 - Wooden lintel on main floor, possibly from the 1840's stable building. The opening is similar in size to the ones visible in the photographs from the 1880s. (Photo: S. Robinson, Heritage Planning)

